


■ Application Use for managing torque of injection screw head (with flat width on both sides).



- Features
 A brass protective plate helps to prevent scratches / damages on the screw head.
 Managing torque helps to prevent damage due to excessive tightening and reduce malfunction.

| Applicable screw outer dia. | Maximum tightening torque (N·m) | Part Number | Unit Price |
|-----------------------------|---------------------------------------|-------------|------------|
| 0~30 | 70 | M-SHA-S | Quotation |
| 30~50 | 160 | M-SHA-M | |

• Follow the standards set by the injection molding machine manufacturer when tightening the torque. During tightening, ensure the wrench does not slip out of alignment.











